



CANADIAN PACIFIC SOUTHERN ONTARIO SERVICE AREA

Conductors, Locomotive Engineers
Yardmen/Trainmen - All Points

ISSUED DATE: December 6, 2007
NOTICE NO.824

*FIELD OPERATIONS- TORONTO YARD
JOINT HEALTH & SAFETY COMMITTEE MEETING*

***Tuesday December 4, 2007: 1000 – 1330
Basement Conference room, GYO Bldg***

COMMITTEE MEMBERS:

N. Richards	Member, Co-chairperson	CPR Co-Chair	Absent
M. Waver	Member	CPR	Present
D. Gillam	Member, Alt Co-chairperson	TCRC/BLE	Present
K. Lawrence	Member	TCRC/UTU/RCLS	Present
P. Grondin	Member	TCRC/UTU	Present
R. Sutton	Member	CPR	Absent
J. Waver	Alternate	CPR	Absent
D. Simpson	Alternate	CPR	Absent
B. Sexsmith	Alternate	TCRC/BLE	Absent

GUESTS Present:

N. Shannon CP Police Services

Agenda:

ITEMS	DESCRIPTION	WHO
1	Review 2007 Safety Plan - Activities	All
2	Review Safety Stats – Personal Injuries, Train Accidents/Incidents	All
3	SOFA Audits	Auditors
4	SOFA Audit Addendum – Sprains & Strains At Risk Factors	Auditors
5	RCLS SOFA Audit Addendum – Toronto Committee Pilot Project	Auditors
6	ORCA Audits	Auditors
7	Footboard Meetings: At-Risk trends, Safety Info-Grams/Flashes	All
8	Monthly Workplace Inspections	Inspectors
9	Accident Investigations/Work Refusals	Participants
10	Safety Hazard Reports	All
11	Old Business/Discussions/Completed Items	All
12	New Business/Discussions,	All
13	Update HRDC/TC Annual Report	All
14	Adjournment	All

Item 1: Review of

H&S Committee reviewed 2007 Safety

Plan and activities: Summary of Activities:

2007 Safety Plan:

Tracking Document

SOSA F.Ops H&S Committee: 2007	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Target	Completed
Safety Activities for 2007					**	***							Month / Yr	Month/Yr
1. SOFA Operations Switching Audits *	5	10	8	8	0	9	15	8	11	11	8		10* / 120*	93
2. SOFA Addendum – Reducing Strains & Sprains *	0	5	1	4	0	0	4	0	0	0	0		PILOT*	14
3. RCLS SOFA Audits Addendum - PILOT *	4	4	5	3	0	4	4	2	1	5	5		PILOT*	37
4. ORCA Audits	2	1	2	1	0	2	1	1	1	0	1		1 Month/12 yr	12
5. Safe Work Practices meetings-blitzes-footboards	1	1	1	1	1	N	1	1	1	1	1		10 Year	10
6. Workplace Inspections	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y		Each area - Twice yearly	On target
7. Pre-Departure Checklist/Job Briefings	Y	Y	Y	Y	Y	N	Y	Y	Y	Y	Y		10 Year	10
8. Mentoring/Coaching Program for Junior employees– (3-5 yrs service) (Pilot Commenced March 2006 and continued in 2007) (#Employees)										1	1		Pilot from 2006	2

*** Total Includes RCLS SOFA Audit Addendum and Strains & Sprains SOFA Addendum**

**** E/S Strike commenced - May H&S Activities Cancelled**

***** E/S Strike continued – June H&S Meeting Cancelled**

Safety Activity 1: SOFA (Switching Operations Fatality Analysis) Audit results:

At-risk procedures (Trends) are identified on SOFA Audits and are discussed. These at-risk items form the topics for discussion in Activity 5: Safe Work Practices, footboard meetings and blitzes.

Safety Activity 2: SOFA Addendum – Reducing Strains & Sprains Audit results:

At-risk procedures (Trends) are identified on SOFA – Reducing Strains & Sprains (Addendum) and are discussed. These at-risk items form the topics for discussion in Activity 5: Safe Work Practices, footboard meetings and blitzes.

Safety Activity 3: RCLS SOFA Audits – PILOT Addendum Audit Results:

At-risk procedures (Trends) are identified on RCLS SOFA Audits (Addendum) and are discussed. These at-risk items form the topics for discussion in Activity 5: Safe Work Practices, footboard meetings and blitzes.

Safety Activity 4: ORCA Audit results:

At-risk procedures (Trends) are identified on ORCA, discussed and form the topics for discussion in Activity 3: Safe Work Practices, footboard meetings and blitzes.

Safety Activity 5: Safe Work Practices, Meetings, Blitzes:

At-risk procedures (Trends) noted in previous month SOFA Audits and/or ORCA audits are discussed with Rte's at following Month's footboard meetings, blitzes and affirm/reaffirm safe work practices and procedures.

Safety Activity 6: Workplace Inspections

Committee to schedule local inspections of Toronto Yard, which includes five (5) Areas: GYO/Hump, Pull down, Classification Yard, Diesel/Car Shop, Arrival/Departure Yards plus seven (8) Customer/Industrial locations: Each area or customer location: established plan is to inspect twice per year.

Safety Activity 7: Pre-Departure Checklist/Job Briefings

Monitor use and quality of pre-departure checklists: monitor and participate in crew job briefings.

Safety Activity 8: Mentoring/Coaching – Continuation of 2006 Pilot Project by Toronto Yard Joint S&H Committee

Description: Development and implementation of mentoring and coaching junior and/or at-risk employees: (Primarily Mentoring Employees between 3-5 years service and/or as otherwise required: Pilot commenced March 2006. Will continue this pilot project as required in 2007.

Item 2: Review Safety Stats – Personal Injuries, Accidents/Incidents: Review To date:

H&S Committee review of SOSA stats and Toronto Yard 2007 – FOPS accidents/Incidents and Personal Injuries:

Tracking Document

					2	0	0	7					2007	2007	2006	2006
FOPS – Toronto Yard	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	YTD Actual	Target	YTD Actual	Target
FRA Personal Injuries	0	0	0	0	1	0	0	0	0	0	0		1	3	3	4
Non-FRA Personal Injuries	1	2	0	0	0	0	0	0	0	0	0		3	7	7	7
FRA Train Accidents	0	0	0	0	0	0	1	0	0	0	0		1	0	0	0
Non- FRA Train Accidents	0	0	0	1*	1	1	0	2	1	0	1		7	11	12	17
Cardinal Rule Violations	0	0	0	1*	0	0	0	0	0	0	0		1	0	3	2

2007

FOPS FRA PI

May 16, 2007 : YSH(Pull Down): Knuckle fell out of car onto top of employees foot – (Broken Knuckle pin)

FRA-LTI(29 days)

FOPS NON-FRA PI

Jan. 20, 2007: P&C YSH – CT14 – Slipped on ladder rung – (Left Leg) – Strained left Knee

NON-FRA

Feb. 04, 2007: P&C YSE - Consumed by Fumes - Eng 1609 (FUMES - REPEATER)

NON-FRA

Feb. 21, 2007: P&C YSH - Consumed by Fumes - Eng 1610 (FUMES)

NON-FRA

FOPS FRA TA

July 23, 2007: PD - Crossed couplers CT07 – Not found by crew as per SSI – Derailed 4 cars on curve - FOPS - FRA

FOPS NON-FRA TA – NIL

Apr. 25, 2007: HUMP – While Traveling down CT17 to pull a-Tracks – Contacted foul car at E/E CT16- Sideswipe:

NON-FRA (CRV) *

May 03, 2007: 223-02: While reversing FL03/FL04 to shop, Eng CSXT7638 Derailed at FL03/FL04: Switch Obstruction under Switch Point-Gap

June 29, 2007: LHF – While coupling to other equipment at LHF with 20 cars – crossed couplers – 1 set wheels CN712157 derailed.

Aug 13, 2007: P&C – 1596-1014 derailed Tapscott Derail – Derail not removed properly.

NON-FRA

Aug 17, 2007: Hump – Pulling out of CT01 – RT AL01 switch

NON-FRA

070929: Finished vehicles jumped chocks while humped in trim mode

FOPS – Non FRA

071121: PCA2 A45/AHML switch run through

FOPS – Non FRA

Cardinal Rules Violations (CRV)

Apr. 25, 2007: HUMP – While Traveling down CT17 to pull a-Tracks – Contacted foul car E/E CT16- Sideswipe

CRV *

Other: incidents reviewed: (NON-HF-FOPS)

Jan. 02, 2007: Hump: Derailment CT01 West End - - Wide Gauge in curve

E/S Responsibility

Jan. 18, 2007: Hump: SOO600369 to Clear track - CT48 – Car through Inert

S&C - HUMP

Jan. 29, 2007: Hump: CT07 – Crossed Couplers – Derailment - - Hump Operation:

S&C - HUMP

Feb 07, 2007: 101-07: Derailed Over switch W/e FT01 – Split Switch: Switch Defect

S&C-E/S

Feb 12, 2007: Hump: NKCR65223 derailed destined GRP 7, acct contacted CEFX10643 which had stalled

S&C - HUMP

Feb.23, 2007: 231-22: Eng 8809 Derailed R7E – Track Wide Gauge/missing Spikes/Rail Anchors

E/S

Mar.01, 2007: Hump: Crossed couplers CT04 - NOKL733645 derailed A-end R3/R4- Hump Operation

S&C - HUMP

Mar.02, 2007: Hump: Over speed ex Master and Group – Oil Contamination in Master

S&C - HUMP

Mar.05, 2007: T14-05- L1/R1 Eng CP8209 derailed account ICE conditions – Trying to break path as per rule –

ENVIRONMENTAL

Mar 24, 2007: Hump: Car to CT27 stalled, next car destined CT15 cornered and derailed b-end of car -

S&C - HUMP

Mar 31, 2007: Hump: Crossed couplers (Hump Operation) in CT25 caused south rail to cant over

S&C - HUMP

Apr 11, 2007: P&C: While reversing in RA02 – Wheel Split switch & Poor switch point

M/S & E/S

Apr 14, 2007: 227-13: Light power reversing into 1E Diesel – CEFX1057 derailed. (B/o Ties)

E/S

Apr 23, 2007: Hump: CT71 Crossed couplers – S. Rail canted southward – 3 cars derailed acct track expanse.

S&C – HUMP

June 21,2007: Hump Operation – Crossed Couplers CT34 – ATW53078 empty – derailed

S&C – HUMP

July 05, 2007: Major Derailment Pull down – Glad hand wedged in frog – 7 cars derailed

Process – M/S

July 28, 2007: Hump Operation – Crossed Couplers CT25 – NS470213 R3/R4 wheels derailed

S&C – HUMP

Aug 12, 2007: Hump Operation - CP 344789 climbed the frog at CT 46-72 and derailed R 1-2 L1-2

E/S

Aug 30, 2007: Hump Operation – Crossed Couplers CT23 – CP570004 R1/R2 wheels derailed

S&C– HUMP

070906: Hump operation – ROIL walkway damaged

Third party

070910: Major derailment B
derailment S&C
070929: 234-29 derailment in east lead of wye
071121: Other impact – CT21/CT27 switch during automatic hump operation

yard – Train 434-07

E/S
S&C

Item 3: SOFA Audit Results:

SOFA Audits: Safe Observations, At-risk observations, SOFA Audit Summary For 2007:

The basic concept of communication, or its lack of, has been attributed to the cause of many Accidents & incidents across the property last year. The key is that we must not assume the other members of our crew know what we are going to do; we must talk about it constantly so we are all sure everyone else is on the same page as us.

SOFA Audit Tracking Document

2007	S	O	F	A			A	U	D	I	T	S	
Lifesaver	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sept	Oct	Nov	Dec	Totals/A VG. YEAR
Lifesaver 1 Secure Equip.	100%	98.6%	100%	100%	0	100%	94.8%	100%	85.7%	98.1%	96.5%		
Lifesaver 2 Equipment	98.2%	100%	98.0%	100%	0	100%	96.6%	100%	96%	97.0%	98.0%		
Lifesaver 3 Job Briefing	96.5%	88.8%	90.0%	100%	0	100%	95.2%	86.6%	100%	85.3%	100%		
Lifesaver 4 Communication	96.5%	93.5%	100%	99.5%	0	100%	95.6%	96.2%	94.4%	95.4%	100%		
Lifesaver 5 Coaching	96.6%	97.7%	97.6%	100%	0	100%	98.1%	95.6%	98.3%	100%	100%		
Total SOFA Conducted /Month	5	10	8	8	0	9	15	8	11	11	8		
Total Audits Month	280	350	386	290	0	278	236	122	243	359	194		
Total - AT Risk Behaviors - Month	8	11	6	1	0	0	9	4	14	13	3		
Overall Totals Month %	97.0%	96.8%	98.4%	99.6%	0	100%	96.1%	96.7%	94.2%	96.4%	98.5%		
Total At Risk % - Month	3.0%	3.2%	1.6%	0.4%	0	0	3.9%	3.3%	5.8%	3.6%	1.5		

Issues/SOFA At Risk Behaviors: Items for discussion:

- SOFA Life (2E) – Testing Handbrake Effectiveness
- SOFA Life (3B) - Proper Job Briefing procedure – (No Use of Toronto Yard Daily job briefing)
- SOFA Life (4C) - Proper radio procedure followed – Use of Engine Numbers
- SOSA Life (1B) – Three Point Protection – One person at a time

Item 4 – SOFA Audit Addendum - Sprains & Strains At-Risk Factors:

Examining additional factors which may lead to sprains and strains:

Sprains & Strains At-Risk Factors Audit Tracking Document

2007 SOFA Audit Addendum - Sprains & Strains At Risk Factors													
	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sept	Oct	Nov	Dec	Totals YEAR
Addendum Conducted /month	0	5	1	4	0	0	4	0	0	0	0		
Total Observations	0	41	21	59	0	0	35	0	0	0	0		
Total AT Risk Behaviors	0	7	1	6	0	0	3	0	0	0	0		
Overall Totals	0	82.9%	95.2%	89.8%	0	0	91.3%	0	0	0	0		
At Risk %	0	17.1%	4.80%	10.2%	0	0	8.7%	0	0	0	0		

Issues/ SOFA Audit Addendum - Sprains & Strains At Risk Factors: Items for discussion:

Nil

Item 5 – RCLS SOFA Audit Addendum – Toronto H&S Committee Local Pilot Project for 2007- RCLS

For 2007, Toronto Yard Joint H&S Committee will commence use of an RCLS SOFA AUDIT addendum an effort to capture and document RCLS operations since most of the yard operations at Toronto Yard are RCLS. (Toronto Yard H&S PILOT ADDENDUM) The purposes of this RCLS tracking sheet are for easy cross reference to identify on the areas of concern that the Toronto Yard Health and Safety Committee may have to address the unique problems in regards to RCLS Operations.

RCLS Tracking Document

2007	<i>R</i>	<i>C</i>	<i>L</i>	<i>S</i>			<i>A</i>	<i>U</i>	<i>D</i>	<i>I</i>	<i>T</i>	<i>S</i>	<i>PILOT</i>
Lifesaver	Jan **	Feb **	Mar **	Apr **	May **	Jun **	Jul ***	Aug	Sept	Oct	Nov	Dec	Totals/A VG. YEAR

Lifesaver 1 Job Briefing	100%	78.7%	94.1%	91.6%	0	88.8%	95.1%	100%	98.6%	94.4%	100%		
Lifesaver 2 Protect Employees Moving Equip.	93.2%	93.5%	98.6%	99.2%	0	96.3%	99.0%	95.2%	96.3%	100%	97.6%		
Lifesaver 3 Secure Equip.	93.3%	100%	95.6%	100%	0	95.4%	88.8%	95.8%	97.5%	96.2%	97.1%		
Lifesaver 4 Communication	90.8%	88%	96.7%	98.8%	0	96.1%	94.0%	97.8%	94.1%	89.7%	100%		
Lifesaver 5 RCLS Operations	--	--	--	--	--	--	100%	88.8%	90.3%	100%	100%		
Total RCLS Conducted /Month	4	4	4	3	0	4	4	2	1	5	5		
Total Audits Month	240	270	398	269	0	438	415	200	289	395	413		
Total - AT Risk Behaviors - Month	17	24	12	3	0	19	16	7	12	13	5		
Overall Totals Month	92.9%	91.1%	96.9%	98.7%	0	95.6%	96.1%	96.5%	95.9%	96.7%	98.8%		
Total At Risk % - Month	7.1 %	8.9 %	3.1%	1.3%	0	4.9%	3.9%	3.5%	4.1%	3.3%	1.2%		

** RCLS SOFA Audit Addendum Draft-1 - (Audit with Four RCLS SOFA Lifesavers) – Used Jan 2007 to June 2007

*** RCLS SOFA Audit Addendum Draft-2 - (Audit with Five RCLS SOFA Lifesavers) – Used commencing July 2007

Issues/RCLS SOFA At Risk Behaviors: Items for discussion:

RCLS/SOFA Life 3 (A) Maintaining three point contact

RCLS/SOFA Life 2 (F) Entraining - Detraining

Item 6 – ORCA Audit Results: (Onboard)

ORCA : On Board - Safe Observations, At-risk observations, ORCA Audit Summary For 2007:

ORCA Audit Tracking Document

2007	O	R	C	A	A				U	D	I	T	S	Totals YEAR
	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sept	Oct	Nov	Dec		
ORCA Conducted /month	2	1	1	1	0	2	1	1		1	0	1		
Total Observations	116	18	180	92	0	230	76	20		38	0	67		

Total AT Risk Behaviors	4	0	0	0	0	0	0	0	0	0	0
		0									
Overall Totals	96.5 %	100%	100%	100%	0	100%	100%	100%	100%	0	100%
At Risk %	3.5%	0%	0%	0%	0	0	0	0	0	0	0

Issues/ORCA At Risk Behaviors: Items for discussion:

No issues.

Item 7: FOOTBOARD Meetings: Summary of items for monthly footboard discussions:

<p>Topics for Footboard Meetings: Including At-risk procedures (trends) identified from previous month: SOFA Audits, Sprain and Strain Addendum, RCLS SOFA Addendum and ORCA audits:</p>
<p>7A)</p> <p>Novemer 2007 SAM'S Message Safety Info-gram – Holiday Season Safety Reminders</p>
<p>7B)</p> <p>At-Risk items: SUMMARY: Trends from: SOFA Audits, Sprain and Strain Addendum, RCLS SOFA Addendum and ORCA audits: Items for discussion:</p> <p><u>Issues/SOFA At Risk Behaviors: Items for discussion:</u> RCLS/SOFA Life 3 (A) Maintaining three point contact RCLS/SOFA Life 2 (F) Entraining - Detraining</p> <p><u>Issues/RCLS SOFA At Risk Behaviors: Items for discussion:</u> RCLS/SOFA Life 3 (A) Maintaining three point contact RCLS/SOFA Life 2 (F) Entraining - Detraining</p> <p><u>Issues/SOFA Audit Addendum - Sprains & Strains At Risk Factors: Items for discussion:</u></p> <ul style="list-style-type: none"> Nil <p><u>Issues/ORCA Audit: Items for discussion:</u></p> <ul style="list-style-type: none"> Nil

NOTE: Footboard meetings commence 0630 Thursday Dec 13 to 0630 Saturday Dec 15, 2007

Item 8: Monthly Workplace Inspections: Any deficiencies noted and being progressed as required.

Monthly Workplace Inspection schedule for 2007:

Workplace Inspection Areas	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
IGI WAX	Plan						Plan					
STRATOFLO	Plan						Plan					
VIVA1-Nelsons - Cross connection	Plan						Plan					

VIVA2-Finch Plant, Owens Corning	Plan							Plan				
Pull down, Ladder, LHF compound	Plan							Plan				
SOLO - (Lily Cup)			Plan						Plan			
IPSCO			Plan						Plan			
Shops - Car/Diesel			Plan						Plan			
Classification Yard				Plan						Plan		
A/B Yards					Plan						Plan	
F/G Yards, Shed/Expressway					Plan						Plan	
GYO/Pull down/Hump/Buildings						Plan						Plan

Item 9: Accident Investigations, Work Refusals,

Accident Investigations (ISROP): Nil
Work Refusals: Nil

Item 10: Safety Hazard Reports Tracking Document:

Tracking Document

2007	Jan	Feb	Mar	Apr	2 May	0 Jun	0 Jul	7 Aug	Sep	Oct	Nov	Dec	YTD
NEW Safety Hazards Received-Month	12	14	08	19	04	08	08	02	02	02	04		
Safety Hazards Resolved	--	08	11	08	12	02	03	08	01	02	03	00	
Safety Hazards Referred for resolve	--	04	03	00	07	02	04	00	01	00	00	04	
Total Hazards Still Outstanding (Year)	--	04	05	02	09	07	10	01	02	02	01	04	

Item 10: Safety Hazard Reports: (Detail): Safety Hazard Reports: 2007: Reviewed and Discussed by Toronto S&H Committee:

Jan 2007:

Jan 03, 2007: #1652: Fumes in Cab Eng 8214 – T04-03 between Toronto Yard and Oshawa >> RESOLVED 01/25/2007
 Jan 05, 2007: #1653: Escalation Request Re: Outstanding tripping hazard #0214 of Sept 24th, 2006 (Rail) >> RESOLVED 01/18/2007
 Jan 13, 2007: #2035: Broken Stairs Hump (Opposite Propane tanks) >> RESOLVED 01/15/2007
 Jan 12, 2007: #2028: Uneven Ballast at Wye Switch Guelph Jct. >> FORWARDED TO HAMILTON/LONDON >> RESOLVED 01/16/2007
 Jan 13, 2007: #2022: Heating in GYO >> NON-SAFETY HAZARD > EXCLUDED >> RESOLVED 01/13/2007
 Jan 18, 2007: #2022: Fumes in Cab Eng 8206 – T14-18 between Toronto Yard and Shed/IGI Wax >> RESOLVED 01/25/2007
 Jan 18, 2007: #2038: FT01 Blue Flag/M/S Five Alive – Procedure Issue >> RESOLVED 01/19/2007
 Jan 18, 2007: #2203: TAXI exception Toronto to Mactier >> FORWARDED To MTL-CALGARY >> RESOLVED 03/01/2007
 Jan 18, 2007: #2037: Rail Lying L1- A-Yard Lead, Stratoflo - (1st HAZARD) >> RESOLVED 04/23/2007
 Jan 29, 2007: #2041: Vines/Brush/Trees north Side Havelock at Stratoflo – Tripping Hazard - (1st HAZARD) >> RESOLVED 07/31/2007
 Jan 30, 2007: #2042: Yard Radio Interference from M/S, E/S, FOPS: Instruction/Reminder Issued >> RESOLVED 02/08/2007
 Jan 30, 2007: #2208: Fumes in CAB P&C Eng 1609 –(2nd REPEAT – Original from Dec 2006)>> See Feb 04,07 >> RESOLVED 04/02/2007
 3rd REPEAT – OUTSTANDING >> See Feb 04, 2007: Hazard #2204

Feb. 2007:

Feb 01, 2007: #2206: Tobacco Residue from Crews Smoking in Engine 1610 – (Eng Inspected – Nil Found) >> RESOLVED 02/01/2007
 Feb 04, 2007: #2204: Fumes in Cab P&C Eng 1548 - #6 Injector Changed, Timing/Rack Adjusted/VEE Cleaned >> RESOLVED 02/19/2007
 Feb 07, 2007: Four Royal Taxi Exceptions for Vehicle Condition (Tires) Sent to CMC/L. Courtney for handling >> RESOLVED 03/07/2007
 Feb 04, 2007: #2204: Fumes in Cab P&C Eng 1609 - (3rd REPEAT) >> RESOLVED 04/02/2007
 Feb 21, 2007: #2207: Fuel Fumes Eng 1610, VEE Groove/Fuel Overflow - MARVIN – MIR – NON-FRA >> RESOLVED 02/23/2007
 Feb 22, 2007: #2049: Timely Deadheading Issue >> Forwarded to CMC for handling >> RESOLVED 02/24/2007
 Feb 24, 2007: #2218: Two Extra Cars on Oshawa "A" – (Shops) – Process/Refocus From Feb 15 to Feb 25 >> RESOLVED 02/25/2007
 Feb 26, 2007: #2219: 8800's Engs – Middle seat – Bar behind head could be a potential hazard> Forwarded >> RESOLVED 03/01/2007
 Feb 27, 2007: #2050: Crew Bus – Burnt out brake light >> RESOLVED 03/01/2007
 Feb 28, 2007: #1615: Inventory Exception – Osh-A Turn >> RESOLVED 03/07/2007

March 2007:

Mar 01, 2007: #2210: Hump Protection of class track CT54: Procedures – Reaffirmed >> RESOLVED
03/07/2007
Mar.02, 2007: #2220: Inventory Exception Osh-B Turn >> RESOLVED 03/08/2007
Mar.02, 2007: #2216: Hallcon Driver Exception – Forwarded to L. Courtney Manager Contractor Services >> RESOLVED 03/08/2007
Mar.04, 2007: #2051: Crew Bus – Burnt out passenger side tail light - arranged to get fixed. >> RESOLVED 03/05/2007
Mar.08, 2007: #2034: Snow/Ice conditions G-Yard Road - Snow Removed March 10/07 >> RESOLVED 03/10/2007
Mar.22, 2007: #2228: CP5878 – Cover for Electrical cover missing – wires exposed >> RESOLVED 04/02/2007
Mar.24, 2007: #2032: Hump trimming in a track, P&C authorized to same track without being advised of hump >> RESOLVED 03/25/2007
Mar.28, 2007: #2229: Oil Burning fumes in Cab – Eng STLH 8212 >> RESOLVED 04/02/2007

April 2007:

Apr 01, 2007: #2230: OCS/ Rail etc on R O W Whitby >> RESOLVED 07/05/2007
Apr 01, 2007: #2231: Condition of F-G Yard Road - Needs Grading >> RESOLVED 05/18/2007
Apr 07, 2007: #2232: Canpa Crossover Switch needs adjustment >> RESOLVED 04/15/2007
Apr 11, 2007: #2233: Crew bus needs netting to hold Grips in place – NON-ISSUE – REVERTED back to vans. >> RESOLVED 05/17/2007
Apr 16, 2007: #2235: Crew bus Hatch Hinges (lid) Broken – (1) >> RESOLVED 04/19/2007
Apr 17, 2007: #2236: Crew bus Hatch Hinges (lid) Broken – (2) >> RESOLVED 04/19/2007
Apr 18, 2007: #2054: Crew bus Hatch Hinges (lid) Broken – (3) (Bus in for repair-19th) >> RESOLVED 04/19/2007
Apr 18, 2007: #2055: Switches E/E of Yard – Need Lubrication >> RESOLVED 05/03/2007
Apr 18, 2007: #2056: Lily Cup/ SOLO Lead – Spike and sinking issues >> RESOLVED 05/10/2007
Apr 18, 2007: #2057: Lily Cup inside switch needs lube or adjustment >> RESOLVED 04/23/2007
Apr 18, 2007: #2058: L4 –into Lily Cup - switch needs lube or adjustment >> RESOLVED 04/23/2007
Apr 18, 2007: #2059: Rail Lying on R O W just west of McCowan Mile 198 >> RESOLVED 11/06/2007
Apr 18, 2007: #2060: Rail Lying near North Track Stratoflo (2nd Hazard Submitted) >> RESOLVED 04/23/2007
Apr 18, 2007: #2061: FGYO Spur Switch needs lube or adjustment >> RESOLVED 04/23/2007
Apr 18, 2007: #2062: L4 – L4A switch needs lube or adjustment >> RESOLVED 04/23/2007
Apr 20, 2007: #2063: Signal Aspect blocked Mile 15 – Galt Sub(Cooksville): FORWARDED- INCL LAMBTON H&S>> Lambton H&S 04/21/07
Apr 28, 2007: #2064: Crew bus Fumes – Coolant Smell >> RESOLVED 04/28/2007
Apr 28, 2007: #2241: Eng 5633 – 233-27 – 234-28 Power defect – swapped in yard >> RESOLVED 04/28/2007
Apr 29, 2007: #2068: Eng 5931- 233-28 Defective ENGM Seat. FORWARDED TO MSA >> RESOLVED 04/29/2007

May 2007:

May 01, 2007: #2242: Condition of F-G Yard Road - Needs Grading (REPEAT Hazard) >> RESOLVED 05/18/2007
May 10, 2007: #2243: Need Whistle post Mile 27 Belleville Sub to Warn people off Bridge: Forwarded Incl MSA H&S >> TO MSA 05/10/07
May 13, 2007: #2246: FUMES – ENGS 8209, 8234 (2nd Emery) >> RESOLVED 05/31/2007
May 30, 2007: #2072: Various Lights burnt out Yard >> RESOLVED 06/12/2007

June 2007:

June 04, 2007:#2294: GBO – No Signals Yet in Place Issue – Belleville Sub (#1) >> RESOLVED 06/09/2007
June 05, 2007:#2260: GBO – No Signals Yet in Place Issue – Belleville Sub (#1) >> RESOLVED 06/09/2007
June 05, 2007:#2293: HUMP BOXES – Flat Switch boxes VS HUMP BOXES >> RESOLVED 06/05/2007
June 21, 2007:#0800: Vines/Brush/Trees- Between Staines and Oahawa – Obscuring signals & ROW >> RESOLVED 07/05/2007
June 21, 2007:#2083: Vines/Brush/Trees- North Side of Lead into IGI WAX – Tripping Hazards >> RESOLVED 07/31/2007
June 21, 2007:#2262: Vines/Brush/Trees- East end SIDING/MAIN OSHAWA >> RESOLVED 07/31/2007
June 21, 2007:#2084: Vines/Brush/Trees- AGIN LEAD – STRATOFLO (2nd Hazard Submitted) >> RESOLVED 07/31/2007
June 30, 2007:#2263: Brush at both ends of GYO tunnel >> RESOLVED 07/05/2007

July 2007:

July 06, 2007: #2085: C1 Escape - L1 Light not working >> RESOLVED 07/09/2007
July 06, 2007: #2086: Weeds/Brush South Main track – IGI Wax >> RESOLVED 07/18/2007
July 06, 2007: #2087: Target LILY- SOLO >> RESOLVED 07/22/2007
July 06, 2007: #2264: Brush Obscuring signals – NTOR- Belleville Sub (Tor Terminals) >> RESOLVED 07/18/2007
July 12, 2007: #2266: Platform 1150 loose - Eng taken to shop for spot weld >> RESOLVED 07/12/2007

July 13, 2007: #2267: Dead restricted site lines hump down to class >> RESOLVED 07/24/2007 Carcass rest switch,
July 17, 2007: #2088: Brush/Weeds in class yard - Sprayed Week of July18-27 >> RESOLVED 07/27/2007
July 19, 2007: #2268: Eroding pavement on top of hill >> RESOLVED 11/13/2007
July 25, 2007: #1484: Brush/weeds Kinnear – REFERRED TO Hamilton E/S and H&S for their follow-up. >> RESOLVED 08/03/2007

Aug 2007:

Aug. 09, 2007: #2354: CP8226-8229, 8231-8252 toilets b/o, Fridges B/o >> RESOLVED 08/15/2007
Aug. 10, 2007: #2352: Lily Cup Issues – Dust/debris >> RESOLVED 08/15/2007

Sept 2007:

Sept. 16, 2007: #2361: McCowan traffic light out of order >>RESOLVED 09/18/2007
Sept. 20, 2007: #2269: hump Shack exterior light off mounting >>RESOLVED10/30/2007

Oct. 2007:

Oct. 03, 2007: #2276: Radio 29958 – Motorola MT2000 – multiple failures >>RESOLVED 11/06/2007
Oct. 12, 2007: #2362: 1684 – Communication Faults >>RESOLVED 10/29/2007

Nov.2007:

Nov. 08, 2007: #2277: Piles of spikes CT yard 8/9 and 29/30 switches >> Referred to ES 071113
Nov. 22, 2007: #2366: Taxi exception >> Referred to CS 071201
Nov. 26, 2007: #2278: CP5863 defects >> Referred to MS 071201
Nov. 30, 2007: #2279: CP5721 defects >> Referred to MS 071130

11: Old Business/Discussions: Status of Items: Completed Items, Reports, Ongoing Items:

NIL

Item 11 - Ongoing Items:

- From Jan 2006 Meeting: Point Protection Hump
Flood point protection hump lead. If signal bungalow malfunction or electrical failures etc what are procedures (K. Lawrence/C. Smith)
K. Lawrence/C. Smith to prepare draft plans for point protection & will present to the Committee.
March 2006 – by default: If no point protection – RCLS rules apply – Issue bulletin (J. Bonham/K. Lawrence)
April 2006: Will review RCLS/GE rules and procedures and draft/issue bulletin:
CAP – J. Bonham/K. Lawrence to have bulletin drafted and issued by June 05
REVISED CAP – J. Bonham/K. Lawrence to have bulletin drafted for issuance by June 30. (ON AV)
REVISED CAP – N. Richards and K. Lawrence to discuss, draft and issue for Sept 30. (AV)
REVISED CAP – N. Richards and K. Lawrence to discuss, draft and issue for Oct. 30. (AV)
REVISED CAP – N. Richards and K. Lawrence to discuss, draft and issue for Dec 31. (C. Smith)
REVISED CAP – C. Smith will draft by Dec 11th for approval and implementation. (D. Humphrey)
Jan 2007: DRAFT 2 Done – A few updates still required
CAP: Proof for Draft-3 for Feb Meeting then draft procedure for training and Implementation.
Feb 2007: Draft Completed – More edits may be required. D. Humphrey will advise for March meeting. (D. Humphrey)
March 2007: REV-CAP – Some issues - Union LR to be followed-up: Have finalized for end April 2007: **ONGOING**
April 2007: No Response received from Union LR. – Ken Lawrence will forward to Craig Watt
May 2007: Concurrence from some received- Will commence rolling out procedure to staff.
July 2007: Rollout Deferred to Fall (Later September/October)

Nov 2007: R. Lewicki to update on date of Roll Out

- From Jan 2007 Meeting:
Terms of reference for 2007 (DRAFT) Reviewed. N Richards will send out electronically. **COMMITTEE DOCUMENTATION**
CAP: Will finalize document for Feb 2007 meeting for signage by members and alternates.
New CAP – March 2007 meeting for signage by members and alternates.
NEW Cap- Further discussion is required before signoff.
Revised CAP: Plan signoff/signage at Sept. meeting. Latest draft send out to all committee members for review
Revised CAP: National contract in progress – will defer. In mean time, status quo with existing terms.
- From July 2007: 6th floor tower – when is renovation being done? – End 2007 early 2008 – Have just been informed that capital for tower renovation has been approved >> Further information to follow as known.

- From Sept 2007: FG-Yard Road worsening. CAP: N. Richards will contact M. Stilwell by Sept 30 to address.
Nov. 2007 – M. Stilwell reports that grading will have to wait to spring 2008 due to ground frozen.
- From October 2007: Best practice
- CAP B. Sexsmith to contact B. Lewicki – P. McGuire with respect to restriction on riding on stairwells of locomotives over a crossing, adjacent to train, converging tracks – explore best practice
- Drawbar Alignment Procedure – Distribute Anderson Ergonomic report to committee – review three (3) Field Ops Ergonomic Guideline videos
Committee asked to provide input to K. Lawrence over the next two weeks to aid in preparing a response to the Anderson Report.

Item 12: New Business /Discussions/Comments: Issues brought forward: 2007:

From November 2007 – Job briefing documentation uploaded to FIT – K. Lawrence to follow up with R. Mokry/P. McGuire.

Item 13: Update HRDC/TC Annual Report:

Yearly update of report for TC due on March 1/2008 for Year 2008.

Committee to review & update HRDC document at end of each monthly meeting.

Next H&S meeting at 1000, Tuesday Jan. 8, 2008 GYO Bldg, 3rd floor Conference Room, Toronto Yard

Signed:

Marc Waver, Alt-Chairperson

D. Gilliam Alt-Chairperson

"If you find that personal problems are having a negative impact on your life, help is available through your Employee and Family Assistance Program (EFAP). To contact the nearest EFAP Referral Agent in your area please call 1-800-735-0286."

George Smith
Service Area Manager
Southern Ontario Service Area